

# SERVICE BULLETIN

**Buell**  
AMERICAN MOTORCYCLES

B-047

August 20, 2002

## SIDESTAND LEG FOR 2003 MODEL FIREBOLT (XB9R) (PRODUCT PROGRAM NO. BP8)

### Purpose

The Buell Motorcycle Company has elected to replace all sidestand legs on XB9R motorcycles, manufactured through July 9th, 2002. The new sidestand provides greater stability to the motorcycle when parked on sloped or uneven surfaces over and above the domestic/international standards with which it originally complied.

### Motorcycles Affected

The motorcycles requiring sidestand leg replacement are identified on the VIN list attached to this bulletin.

### Replacement Sidestand Legs

The part will be available on or before August 21, 2002. Part must be ordered as required and purchase price will be reimbursed through the warranty system. See CREDIT PROCEDURES. The replacement sidestand leg Part No. is: L0167.02A8.

### Customer Notification

Because only registered owners, as shown on the attached list, will receive notification from us, we request that you contact owners of vehicles still listed as unregistered, advise them of this Program and make arrangements with them to come in for the offered services.

### Required Dealer Action

Check VIN list for motorcycles that were shipped to or sold by your dealership. If your dealership has in stock or has sold any of the motorcycles on the VIN list, perform all actions required by this Bulletin.




Figure 1. Sidestand Leg




Figure 2. Old and New Sidestand Legs

### IMPORTANT NOTE

In the interest of preserving customer safety and satisfaction, always check for outstanding recalls whenever any motorcycle is brought into your dealership for either maintenance or service.

ROUTING	SERVICE MANAGER	SALES MANAGER	PARTS MANAGER	LEAD TECHNICIAN	TECHNICIAN NO.1	TECHNICIAN NO.2	TECHNICIAN NO.3	TECHNICIAN NO.4	RETURN THIS TO
INITIAL HERE									

©2002 Buell Motorcycle Company