

CHRONOLOGY OF EVENTS:

Late April, 2006 field reports on 2006 Ulysses model motorcycle sidestand failures, led to an investigation of warranty data and customer contact data. The investigation resulted in Buell Distribution Company, LLC declaring a safety recall on June 29, 2006.

DESCRIPTION OF THE PROGRAM TO REMEDY THE DEFECT:

The correction for this issue is to replace the sidestand assembly and fasteners.

BUELL PRE-NOTIFICATION REMEDY REIMBURSEMENT PROGRAM:

Buell incorporates by reference herein the general reimbursement plan it has previously provided to NHTSA for reimbursing customers for remedy costs incurred prior to notification of this recall.

PART 577 NOTICE LETTER:

A draft of the owner notification letter is attached.

Please advise the undersigned of the campaign number assigned by ODI to this recall.

Sincerely,



Ronald L. Mundt
For Buell Distribution Company, LLC