

RANKING	DTC	CHECK ENGINE LAMP CODE	FAULT CONDITION	SOLUTION
41	P0506	34	Idle Air Control System - RPM Higher Than Expected	<a href="#">2.24 DTC P0506 (34), P0507 (34), P0511 (34)</a>
42	P0507	34	Idle Air Control System - RPM Lower Than Expected	<a href="#">2.24 DTC P0506 (34), P0507 (34), P0511 (34)</a>
43	P0692	36	Fan Control Circuit High	<a href="#">2.29 DTC P0691 (36), P0692 (36)</a>
44	P0691	36	Fan Control Circuit Low	<a href="#">2.29 DTC P0691 (36), P0692 (36)</a>
45	P0617	46	Starter Relay Circuit High	<a href="#">2.27 DTC P0617 (46)</a>
46	P1112	22	Active Intake Control Throttle Position Sensor Feedback Failure	<a href="#">2.30 DTC P1110 (22), P1111 (22), P1112 (22) (JAPANESE MODELS ONLY)</a>
47	P1111	22	Active Intake Control Circuit Short High	<a href="#">2.30 DTC P1110 (22), P1111 (22), P1112 (22) (JAPANESE MODELS ONLY)</a>
48	P1110	22	Active Intake Control Circuit Short Low/Open	<a href="#">2.30 DTC P1110 (22), P1111 (22), P1112 (22) (JAPANESE MODELS ONLY)</a>
49	P1601	47	Auxiliary Relay Driver Circuit	<a href="#">2.35 DTC P1601 (47)</a>
50	P0608	37	Vehicle Speed Sensor Control Module Fail	<a href="#">2.36 DTC P1653 (35), P1654 (35)</a>
51	P1654	35	Tachometer Output High	<a href="#">2.36 DTC P1653 (35), P1654 (35)</a>
52	P1653	35	Tachometer Output Low	<a href="#">2.36 DTC P1653 (35), P1654 (35)</a>