

# SERVICE BULLETIN



B-102

May 23, 2011

---

## 2009-2010 Buell 1125 Models Charging System Specifications Correction

### Purpose

The purpose of this bulletin is to inform Buell service dealers of an incorrect specification in the 2009 and 2010 Buell 1125 models electrical diagnostic manuals. In these publications the stator AC output specification is incorrect. For 2009 and 2010 Buell 1125 models, the correct AC output is 35-45 Volts AC.

### Vehicles Affected

This information applies to all 2009-2010 Buell 1125 model or 2008 1125Rs with the 2009-10 charging system installed.

### Markets Affected

All markets are affected.

### Required Dealer Action

#### *NOTE*

*Make the following changes in all language variations.*

Change the AC output specification to 35-45 Volts AC in the following Buell 1125 electrical diagnostic manuals:

#### **2009 Buell 1125 Models Electrical Diagnostic Manual (Part No. 99949-09Y)**

3.3 CHARGING SYSTEM DIAGNOSTICS, Testing, AC Output Check, step 1, c.

#### **2010 Buell 1125 Models Electrical Diagnostic Manual (Part No. 99949-10Y)**

3.5 CHARGING SYSTEM, Battery Charging Tests, AC Output Check, step 1, c.