

Credit Procedures

After servicing each vehicle, complete a regular warranty claim referencing Service Bulletin B-047 in the "Description of Repair" section of the claim. Fill in the rest of the claim as follows:

CLAIM TYPE	BP8
QUANTITY	0
PROBLEM PART NO., Evl. 1	L0194.02A8A
PART DESCRIPTION	sidestand leg
ADDITIONAL PART QTY., Evl. 1	1
ADDITIONAL PART NO.	L0167.02A8
ADDITIONAL PARTS DESCRIPTION	sidestand leg
PRIMARY LABOR CODE	2349
TIME	0.2 HOUR
CUSTOMER CONCERN CODE	9203
CONDITION CODE	9111

Upon receipt and processing of claim, you will receive appropriate credit for parts and labor. Destroy and discard replaced sidestand leg.