



DEALER COMMUNICATIONS
Buell Motorcycle Company

September 30, 2002

Subject: SAFETY RECALL CAMPAIGN 0825

Dear Buell Dealer:

Buell Distribution Company, LLC has decided that there is a safety defect with the side stands on 2003 Buell Firebolt XB9R Motorcycles built on 8-6-02 through 9-4-02 which causes them to have the potential to bend or break. Side stand legs which have been shipped for use in Buell Product Program No. 8 [BP8], also may have the potential to bend or break. It has been determined that the correction of the condition can be accomplished by installation of a new side stand leg.

We have voluntarily declared this a defect related to motor vehicle safety (Campaign 0825) to allow us to formally recall all potentially affected motorcycles. A bulletin containing details, including parts availability and instructions on disposition of existing inventory, will follow in approximately 15 working days.

In the interest of the safety of our mutual customers and as required by law, you may sell but **NOT DELIVER** any affected motorcycles to your customers until the recall service has been performed.

In accordance with Federal regulations administered by NHTSA, Buell Distribution Company will provide notice to all owners of record of affected products with direction to bring the vehicle in for the recall service.

Sincerely,

Buell Distribution Company, LLC